

OP[TINA LAJKOVAC						
INDUSTRIJSKA ZONA						
ELEMENTI KRIVINA TEMENIH TA^AKA						
Тип тачке	Број тачке	Elementi krivina				
		α	R	Tg	B	Lk
		[° ' "]	[m]	[m]	[m]	[m]
T	1	08 07 56	75.00	5.33	0.19	10.64
T	2	105 40 34	20.00	26.38	13.11	36.89
T	3	04 06 57	35.00	1.26	0.02	2.51
T	5	31 55 59	100.00	28.61	4.01	55.73
T	6	91 13 47	35.00	35.76	15.04	55.73
Тр	7	33 52 42	160.00	48.73	7.26	94.60
T	8	36 57 22	59.00	19.72	3.21	38.06
T	9	02 38 20	600.00	13.82	0.16	27.63
T	13	06 25 51	105.00	5.90	0.17	11.78
T	14	09 23 58	150.00	12.33	0.50	24.61
T	15					
T	16	25 40 44	95.00	21.65	2.44	42.58
T	18	07 42 29	90.25	6.08	0.20	12.14
T	19	11 10 53	150.00	14.68	0.72	29.27
T	20	05 16 44	250.00	11.52	0.26	23.03
T	21	95 17 39	19.75	21.66	9.56	32.85
T_M	23	84 00 51	225.00	202.64	77.80	329.92
T	24	01 57 48	2000.00	34.27	0.29	68.53
T_M	28	57 48 58	150.00	82.83	21.35	151.36
Т пр	29	03 11 14	300.00	8.35	0.12	16.69
T	32	89 56 37	25.00	24.97	10.34	39.24
T	33	78 18 48	17.50	14.25	5.07	23.92
T	34	35 49 08	45.00	14.54	2.29	28.13
T	35	12 08 22	45.00	4.78	0.25	9.53
T	36	37 24 38	45.00	15.24	2.51	29.38
Т пр	37	06 17 07	300.00	16.47	0.45	32.91
T	39	19 09 46	45.00	7.60	0.64	15.05
T	40	54 28 00	75.00	38.60	9.35	71.30
Т пр	42	03 19 59	450.00	13.09	0.19	26.18
T	43	38 37 41	170.00	59.58	10.14	114.61
T_M	44	04 00 04	1500.00	52.40	0.91	104.75
T_M	51	10 48 06	400.00	37.82	1.78	75.41
T	56	18 26 52	350.00	56.84	4.58	112.69
T	60	89 01 44	35.00	34.41	14.08	54.38
T_M	70	14 57 54	800.00	105.07	6.87	208.95
T	71	15 21 37	350.00	47.20	3.17	93.83
T	74	16 10 18	150.00	21.31	1.51	42.34
T_M	79	06 32 43	800.00	45.74	1.31	91.39
T	81	63 41 12	350.00	215.62	62.01	389.04
T	85	18 10 19	60.00	9.59	0.76	19.03
Т пр	86	51 49 26	430.00	208.91	47.86	388.93
T	87	11 05 12	45.00	4.37	0.21	8.71
T	91	44 44 51	30.00	12.35	2.44	23.43
T	92	28 42 29	25.00	6.4	0.81	12.53
T_M	93	77 38 31	160.00	128.74	45.36	216.82

OP[TINA LAJKOVAC						
INDUSTRIJSKA ZONA						
ELEMENTI KRIVINA TEMENIH TA^AKA						
Тип тачке	Број тачке	Elementi krivina				
		α	R	Tg	B	Lk
		[° ' "]	[m]	[m]	[m]	[m]
T	94	40 39 38	179.00	66.32	11.89	127.03
T	95	33 02 47	75.00	22.25	2.23	43.26
T	96	74 08 44	465.00	351.33	117.8	601.75
T_M	98	51 59 34	130.00	63.4	14.63	117.97
T	99	130 16 08	17.50	37.76	24.12	39.79
T	103	23 44 06	45.00	9.46	0.98	18.64
T	104	04 21 48	250.00	9.52	0.18	19.04
T	105	18 41 33	450.00	74.06	6.05	146.81
T	107	10 58 17	450.00	43.22	2.07	86.17
T	108	97 53 36	20.00	22.96	10.45	34.17
T	109	17 51 31	450.00	70.7	5.52	140.26
T	110	03 34 09	450.00	14.02	0.22	28.03
T	111	09 47 37	30.00	2.57	0.11	5.13
T	112	07 37 55	30.00	2.00	0.07	3.40
T	113	12 47 19	60.00	6.72	0.38	13.39
T	114	2 54 23	150.00	3.81	0.05	7.61
T	115	08 40 14	130.75	9.91	0.38	19.79
T	116	105 11 11	9.00	11.77	5.82	16.52
T	117	92 12 37	9.00	9.35	3.98	14.48
T	118	95 24 40	17.50	19.24	8.5	29.14
T	121	04 35 21	650.00	26.05	0.52	52.06
T	122	03 56 19	1500.00	51.58	0.89	103.11
T	123	00 55 30				
T	124	00 20 43				
T	125	18 21 46	75.00	12.12	0.97	24.04