

OP[ITINA LAJKOVAC				
INDUSTRIJSKA ZONA				
СПИСАК КООРДИНАТА ТАЧАКА САОБРАЈАЈА				
Тип тачке	Број тачке	Координате		
		Y	X	
		[ m ]	[ m ]	
T	1	33984.14	14083.67	
T	2	34019.27	13966.08	
T	3	34063.77	14044.41	
O	4	34066.08	14047.88	
T	5	34068.11	14158.09	
T	6	34084.98	14170.00	
Tr	7	34088.50	14187.74	
T	8	34089.87	14083.53	
T	9	34098.46	13946.45	
O	10	34099.91	14163.47	
T	11	34109.55	14248.10	
T	12	34130.01	14218.26	
T	13	34146.22	14031.52	
T	14	34180.15	13930.15	
T	15	34197.91	14217.53	
T	16	34235.34	13928.33	
O	17	34261.95	13993.98	
T	18	34269.27	13910.61	
T	19	34273.70	14203.44	
T	20	34283.81	14172.54	
T	21	34316.33	13893.62	
O	22	34332.96	14175.06	
T_M	23	34342.55	14537.82	
T	24	34423.52	14179.68	
O	25	34465.16	14205.60	
O	26	34465.59	14180.39	
O	27	34565.89	14206.74	
T_M	28	34616.34	14197.70	
Tr	29	34619.14	14198.03	
O	30	34632.41	14183.19	
O	31	34637.92	14148.23	
T	32	34640.83	14319.95	
T	33	34669.90	14226.24	
T	34	34664.29	14008.85	
T	35	34664.92	13928.49	
T	36	34676.60	14055.60	
Tr	37	34678.47	14195.87	
O	38	34686.86	13950.27	
T	39	34703.66	13906.66	
T	40	34757.50	14327.59	
O	41	34774.91	14352.57	
Tr	42	34790.68	14204.13	
T	43	34826.59	14423.75	
T_M	44	34843.14	14224.14	
T	45	34945.69	14439.22	

OP[ITINA LAJKOVAC				
INDUSTRIJSKA ZONA				
СПИСАК КООРДИНАТА ТАЧАКА САОБРАЈАЈА				
Тип тачке	Број тачке	Координате		
		Y	X	
		[ m ]	[ m ]	
O 46		34951.23	14216.59	
O 47		34955.73	14447.59	
T 48		35001.86	14485.08	
O 49		35028.35	14324.90	
O 50		35063.59	14265.35	
T_M 51		35087.00	14270.00	
O 52		35094.13	14340.33	
O 53		35096.02	14193.57	
T 54		35118.59	14410.87	
O 55		35127.69	14475.69	
T 56		35134.22	14102.47	
O 57		35161.60	14071.73	
T 58		35184.51	14289.99	
O 59		35235.81	14178.16	
T 60		35246.34	13882.15	
O 61		35257.62	14269.55	
O 62		35261.47	14226.57	
O 63		35262.73	14212.52	
O 64		35264.47	14193.15	
O 65		35264.99	14187.39	
O 66		35267.22	14162.46	
O 67		35294.24	13928.36	
O 68		35294.19	14176.00	
T 69		35387.53	14289.46	
T_M 70		35390.14	14269.20	
T 71		35400.79	14031.15	
O 72		35467.41	14203.70	
T 73		35516.89	14451.69	
T 74		35565.43	14134.97	
O 75		35573.03	14125.09	
T 76		35585.23	14365.12	
O 77		35590.53	14342.04	
T 78		35595.14	14344.36	
T_M 79		35599.20	14324.49	
O 80		35661.31	14015.67	
T 81		35443.27	13988.90	
O 82		35804.04	14168.29	
O 83		35828.79	14368.91	
O 84		35829.21	14369.85	
T 85		35835.29	14383.48	
T_pr 86		35838.65	14222.30	
T 87		35859.21	14409.86	
O 88		35868.02	14133.87	
O 89		35869.09	14417.26	
O 90		35876.29	14146.10	

OP[ITINA LAJKOVAC				
INDUSTRIJSKA ZONA				
СПИСАК КООРДИНАТА ТАЧАКА САОБРАЈАЈА				
Тип тачке	Број тачке	Координате		
		Y	X	
		[ m ]	[ m ]	
T 91		35877.91	14423.80	
T 92		35881.18	14445.54	
T_M 93		35904.38	14368.84	
T 94		35897.55	14356.35	
T 95		35927.17	14411.22	
T 96		35954.11	14217.81	
O 97		36004.62	13998.77	
T_M 98		36044.43	13996.77	
T 99		36054.14	14011.43	
O 100		36163.63	14202.31	
O 101		34235.23	13925.84	
O 102		36000.99	14022.75	
T 103		36216.76	14286.59	
T 104		34225.65	14174.93	
T 105		36026.86	14002.27	
O 106		34465.34	14195.05	
T 107		35823.12	14202.95	
T 108		35891.88	14169.15	
T 109		35688.05	14239.67	
T 110		35427.98	14227.62	
T 111		35283.04	14229.94	
T 112		35259.08	14226.20	
T 113		34675.91	14327.81	
T 114		34653.97	14261.02	
T 115		34686.75	14225.29	
T 116		34758.86	14233.69	
T 117		34748.52	14259.49	
T 118		34808.41	14280.85	
T 119		35284.00	14464.04	
T 120		35798.75	14373.95	
T 121		36040.28	14319.68	
T 122		35235.21	13987.10	
T 123		35131.84	14223.43	
T 124		34665.76	14183.75	
T 125		35947.56	14294.56	